PHOTOGRAPHIC DOCUMENTATION

INDEX TO PHOTOGRAPHS

Scholle Farm House Springville and Ponderosa Drives Camarillo Ventura County

Photography by Dennis Hill, August 2021		
Photo 1	Contextual view of residence and out buildings from Springville Drive and on-ramp to US Highway 101, looking northeast.	
Photo 2	Contextual view of farm area west of main residence from Springville Drive and on-ramp to US Highway 101, looking west.	
Photo 3	Contextual view of farming area west of main residence from Springville Drive and on-ramp to US Highway 101, looking west southwest.	
Photo 4	Contextual view of main residence and out buildings from the intersection of Springville and West Ponderosa Drives, looking west.	
Photo 5	Contextual view of main residence and out buildings from uphill area north of main residence, looking southwest.	
Photo 6	Contextual view of eastern portion ranch area with US Highway 101 in distance, looking southwest.	
Photo 7	Contextual view of northwestern portion of ranch area, looking northwest.	
Photo 8	Contextual view of northeaster portion of ranch area with main residence and outbuildings, looking northeast.	
Photo 9	Contextual view of eastern portion of ranch area with main residence and adjacent housing in background.	
Photo 10	Elevation view of south façade of main residence, looking north.	
Photo 11	Detail view of south (main) entrance and decorative gable, looking up in a northerly direction.	
Photo 12	Oblique view of south (main) entrance and west facing façade, looking northeast.	
Photo 13	Detail view of west façade at the southern end, showing secondary entrance and bay windows.	
Photo 14	Elevation view of north façade showing secondary porch, looking south.	

Photo 15	Detail oblique view of north façade secondary porch entrance, looking southeast.
Photo 16	Elevation view of east façade, looking west.
Photo 17	Oblique view of south and east façades, looking northeast.
Photo 18	Interior view porch on south façade, looking east.
Photo 19	Interior view of main room from entry showing room with bay windows and kitchen, northwest
Photo 20	Interior view of room with bay windows, looking west.
Photo 21	Interior view of kitchen area showing built-in cupboard and ironing board, looking towards main interior room, looking southeast.
Photo 22	Interior view of hall, looking towards secondary porch, looking north.
Photo 23	View of outbuilding adjacent to main residence, looking northwest.
Photo 24	Detail view south façade of outbuilding showing door tracking system, looking north.
Photo 25	View of two collapsed outbuildings adjacent to main residence, looking southwest.
Photo 26	View of two collapsed outbuildings adjacent to main residence, looking north.
Photo 27	View of outbuilding adjacent to main residence showing north and east façades, looking southwest.
Photo 28	View of outbuilding used for cooking showing east façade, looking west.
Photo 29	View of outbuilding used for cooking showing south façade, looking north.
Photo 30	Interior view of outbuilding used for cooking, looking northwest.
























Photo 11







Photo 14



Photo 15
















Photo 22





Photo 24

















Scholle_HABS_Digital_01



Scholle_HABS_Digital_02





Scholle_HABS_Digital_04





Scholle_HABS_Digital_06



Scholle_HABS_Digital_07



Scholle_HABS_Digital_08



Scholle_HABS_Digital_09












Scholle_HABS_Digital_14










Scholle_HABS_Digital_18




Scholle_HABS_Digital_19



Scholle_HABS_Digital_20



Scholle_HABS_Digital_21




Scholle_HABS_Digital_22



Scholle_HABS_Digital_23









Scholle_HABS_Digital_27





