



FRONT PORCH AND WOOD DECK

County of Ventura  
August 29, 2022  
Cultural Heritage Board Meeting  
Item 10a  
Exhibit 3 – Site Photos

1057 Briggs Rd.



UTILITY ROOM

1057 Briggs Rd.



TYPICAL CONCRETE FOUNDATION WALL CONDITION

1057 Briggs Rd.



TYPICAL SAGGING CONSTRUCTION CONDITIONS

1057 Briggs Rd.



TYPICAL CONCRETE FOUNDATION WALL CONDITION

1057 Briggs Rd.



EAST ELEVATION

1057 Briggs Rd.



SOUTH ELEVATION

1057 Briggs Rd.



NORTH ELEVATION

1057 Briggs Rd.





NORTH ELEVATION

1057 Briggs Rd.



FRONT PORCH ROOF

1057 Briggs Rd.



UTILITY ROOM ROOF - NORTH ELEVATION

1057 Briggs Rd.



TYPICAL CONCRETE FOUNDATION WALL CONDITION

1057 Briggs Rd.



TYPICAL CONCRETE FOUNDATION WALL CONDITION

1057 Briggs Rd.



CONCRETE DRIVEWAY/PARKING AREA

1057 Briggs Rd.



CONCRETE WALKWAY AND GRASSY AREA

1057 Briggs Rd.



SOUTHWEST CORNER OF CORRUGATED METAL GARAGE BUILDING

1057 Briggs Rd.





NORTHWEST CORNER OF CORRUGATED METAL GARAGE BUILDING

1057 Briggs Rd.



CORREGATED METAL GARAGE BUILDING

1057 Briggs Rd.