

## SITE IDENTIFICATION FORM

Initial I.D. N Follow-up Investigation Y

### SITE INFORMATION (ID #51)

Site Name: CAMARILLO DUMP SWIS: 56-CR-0046 County: 56 Parcel #'s: 171-0-250-450; 171-31-312-1 through 4; 171-31-311-1 through 5; 171-31-313-17 through 35. Tract 4433 Lots 27-35, 129-137.

Location: Homesites on Via Pacheco and Paseo Montelena

Land Owner: Multiple

Address: Multiple

City: Camarillo State: CA Zip: 93010 Phone: N/A Types of Waste: Normal household refuse  
Site Type: Burn Dump

Disposal Area: 4.65 acres SWFP Date: N/A WDR # N/A

Dates of Operation: Closed Feb.1954 Closure Approved By: N/A

Land Use on or Within 1000 ft; 1 mile of waste boundary:

Single Family Homes

### OBSERVATIONS

Date of Field Visit: 6/25/97 Sig. Change Since Last Visit? N

Surface Condition: Single Family Homes

Landfill gas: None Detected

Leachate: None Observed

Other: Solid waste that was burned and disposed of was apparently removed or displaced by nature. The disposal area was adjacent to the Calleguas Creek.

### EXPLANATION

Geotechnical reports and investigations (W.O. 7606) dated 1/2/89 conducted by Geo Labs for the development of this Tract showed that this area was used as a borrow site for fill soil for off-site projects from 1979-89. In certain areas sixty feet of soil was removed. No solid waste was encountered. All material was native soil. Additional trenches and borings for this Tract showed

all soil, no solid waste was encountered. Geotechnical reports are maintained at the City of Camarillo, Engineering Department. See attached summary for documentation on research. Site inspections by the LEA during February 1982 showed no evidence of solid waste at the former disposal area and surrounding subdivision.

#### RECOMMENDATION

Emergency Response: N/A Other: ARCHIVE. Eliminate from the required inspection frequency.

Reassess Site: No No Further Action: Archive Priority for Site Assessment: N/A

Prepared By: Barry Marczuk - LEA Date: 6/26/97

CIWMB Approval: