

SITE IDENTIFICATION FORM

Initial I.D. N Follow-up Investigation N

SITE INFORMATION (ID #48)

Site Name: Coyote Canyon AKA:

SWIS: 56-CR-0043 County: 56 Parcel #'s 110-0-170-415 Location: 2800 Berylwood Road

Land Owner: John Borchard

Address: 2800 Berylwood Road

City: Somis State: CA Zip: 93066 Phone:

Types of Waste: Brush, automobiles, household trash, rubbish Site Type:

Disposal Area: unknown SWFP Date: N/A WDR # N/A Dates of Operation: Unknown Closure  
Approved By: N/A

Land Use on or Within 1000 ft; 1 mile of waste boundary:

Aggricultural

OBSERVATIONS

Date of Field Visit: 05/28/98 Sig. Change Since Last Visit? Y

Surface Condition: Waste has been removed

Landfill gas: N/A Leachate: N/A Other: N/A

EXPLANATION

The LEA issued a Notice of Violation to John Borchard on March 28, 1990 requiring removal of all accumulated solid waste from the property. The LEA completed a final inspection on May 28, 1998 and determined all waste has been removed and the site is clean closed.

RECOMMENDATION

Emergency Response: N/A Other: ARCHIVE. Eliminate from the required inspection frequency.

Reassess Site: No No Further Action: Priority for Site Assessment: N/A

Prepared By: Nadia Emanuel Date: June 4, 1998