## SITE IDENTIFICATION FORM

Initial I.D. (Y/N): N Follow-up Investigation (Y/N): Y

SITE INFORMATION (ID#4)

Site Name: CROFT SITE

AKA:

SWIS #:56-CR-0004 County: Ventura Parcel #(s): Unknown

Location: South of Stauffer Road, Lockwood Valley R21W,77N

Land Owner(s): Unknown

Address: Unknown

City: Unincorporated State: CA Zip: Ukn Phone: Ukn

Types of Waste: Unknown

Site Type: Closed Refuse Disposal Site

Disposal Area (Acre): Unknown SWFP Date: N/A WDR Number: N/A

Dates of Operations: Closed 1964 Closure Approved By: N/A

Land Use on or Within 1000 ft; 1 mile of boundary: Unknown

**OBSERVATIONS** 

Date of Field Visit: N/A Sig. Change Since Last Visit? (Y/N/NA): N/A Surface Condition: N/A

Landfill Gas: N/A

Leachate: N/A

Other:

**EXPLANATION** 

This site has not been located. Record search has revealed an approximate location of range and township. The site was initially identified in the 1975 V.C. CoSWMP. The extent of identification is a dot on a map. See attached summary for documentation on location research.

RECOMMENDATION

Emergency Response: N/A Other: If location is identified an updated SIF will be completed

Reassess Site? (Y/N/NA): N/A No Further Action? (D Priority Y/N): Insufficient information is presently available to allow for the location of this site. It is recommended that the site be archived until additional information becomes available for the location of this site. Eliminate this site from the required inspection frequency.

Priority for Site Assessment (High/Med/Low): N/A

Prepared By: Barry Marczuk -LEA Date: 8/16/95 CIWMB Approval: C&R Branch 2/7/96